

Asian Institute of Technology

Km. 42 Paholyothin Highway, Klong Luang, Pathumthani, Thailand 12120

P. O. Box 4 Klong Luang, Pathumthani 12120, Thailand. Tel. (66-2) 524-5527, 524-6427 Fax.(66-2) 524-5544

STRUCTURAL ENGINEERING LABORATORY
STRUCTURAL ENGINEERING FIELD OF STUDY
SCHOOL OF ENGINEERING AND TECHNOLOGY

TYPE OF TEST:

PULL-OUT TEST IN AXIAL TENSION

TEST SPECIMEN:

Three (3) specimens of "Iccons Stud Grade 5.8 M24x300" bonded with "Iccons VDP-Q (Chemical Capsule) M24" in concrete blocks having a

size of 400 x 1,200 x 1,200 mm. were tested.

CLIENT:

ICCONS (THAILAND) CO., LTD.

DATE OF TEST:

October 26, 2015

TEST RESULTS:

ขนาดดอก ความลึก สว่านที่ใช้ ของรูเจาะ สามารถรับน้ำ หนักได้ต่อจุด

Specimen	Туре	Diameter	Depth	Span	Maximum	Mode of Failure
No.	of Specimen	of Drill hole (mm.)	of Drill hole (mm.)	Length (mm.)	Load (kg.)	แท่งเกลียวเหล็กขาด หรือคอนกรีตแตก เมื่อรับกำลังสูงสุดประมาณ 26 ตัน
2	Iccons Stud M24x300	26	210	300	26,590	-The anchor stud failure occurred when applied the maximum load.
3	Iccons Stud M24x300	26	210	300	26,370	-The failure occurred due to concrete breakout when applied the maximum load.

Note: This report certifies the adequacy and representative character of the test sample(s) only.

TESTED BY:

MR. SAMWAI SORNSRIDA TECHNICIAN

CHECKED BY:

APPROVED BY:

PROFESSOR PENNUNG WARNITCHAI FIELD COORDINATOR OF STE/SET

November 5, 2015

MR. EKKACHAI YOOPRASERTCHAI RESEARCH ASSOCIATE CLIENT: ICCONS (THAILAND) CO., LTD.

DATE OF TEST: October 26, 2015

 TEST RESULTS:
 ขนาดดอก
 ความลึก
 สามารถรับน้ำ

 สว่านที่ใช้
 ของรูเจาะ
 หนักได้ต่อจุด

Specimen		Diameter	Depth	Span	Maximum	Mode of Failure
No.	of Specimen	of Drill hole (mm.)	of Drill hole (mm.)	Length (mm.)	Load (kg.)	แท่งเกลียวเหล็กขาด หรือคอนกรีตแตก เมื่อรับกำลังสูงสุดประมาณ 26 ตัน
1	Iccons Stud M24x300	26	210	300	27,140	-The anchor stud failure occurred when applied the maximum load.
2	Iccons Stud M24x300	26	210	300	26,590	-The anchor stud failure occurred when applied the maximum load.
3	Iccons Stud M24x300	26	210	300	26,370	-The failure occurred due to concrete breakout when applied the maximum load.